


X-Ray Eyes

Infrared Scanning
For All Your Unseen Problems

IR Info	Value
IrNo	1
ems	1
dist	2
Label	Value
P01:T	
emp	60.59
S01:M	-----



This is a pitcher of an electrical in-floor heat system that had a brake in the factory wire harness. The electrician spent five hours trying to find the brake. The tile layer told him about our company then they gave us a call. We came out to the job site and with the electrician's help and our thermal camera we found the problem area in ten minutes.

